

Work Order ID 62845



Page 1

October 12, 2010 9:19:23 AM

Item ID: D412-724-041

Accept



Setup Start



Revision ID:

Stop



Item Name: Head Rest Assembly, Center

Start Date: 10/13/10 Start Qty: 2.00



Cust Item ID:

Required Date: 10/14/10 Req'd Qty: 2.00



Customer:

Reference:

Approvals:

Process Plan:

Handwritten signature

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

N/A

Rev N/A

100

0.00



DC

DOCUMENT CONTROL

Memo

0.00

Document Control

If D412-724-041 is a W/O on it's own, ☐ Photocopy bluefile and create labels per
PPP D412-724-041 CHG001

Handwritten: S 10/11/02
Handwritten: S 10/11/02
Handwritten: 10/11/02

110

0.00



Packaging

Pick Kit

Memo

0.00

Packaging

Handwritten: 10/11/2010
Handwritten: RD

120

0.00



QC

QC4- 100% Inspect kits for completeness

Memo

0.00

Quality Control

Handwritten: S 10/11/02

Handwritten: (X2)

Work Order ID 62845

October 12, 2010 9:19:24 AM



Page 2

Item ID: D412-724-041

Accept



Setup Start



Revision ID:

Stop



Item Name: Head Rest Assembly, Center

Start Date: 10/13/10 Start Qty: 2.00



Cust Item ID:

Required Date: 10/14/10 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130

0.00



Packaging

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D412-724

041 ☐ Location: _____ ☐ PPP Rev: _____

Signature
10/14/10 (2)

140

0.00



QC21- Final Inspection - Work Order Release

QC

Memo

0.00

Quality Control

Signature
10/11/03

MF
10-11-3

Picklist Print

October 12, 2010 9:19:17 AM

Page 1

Work Order ID: 62845

Parent Item: D412-724-041

Parent Item Name: Head Rest Assembly, Center



Start Date: 10/13/10

Required Date: 10/14/10

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev:A 04.09.08 New Issue KJ/JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

AN525-10R6

Purchased

No

120

Each

160.0000

4

8

Screw

Location

Loc Qty

Loc Code

ST325

160

113524

160

D3303-041

Manufactured

No

120

Each

1.0000

1

2

Head Rest

Location

Loc Qty

Loc Code

ST186

1

60863

1

D3304-041

Manufactured

No

120

Each

11.0000

1

2

Tube Assembly

Location

Loc Qty

Loc Code

ST187

11

54438

11

3.0 INSTALLATION PROCEDURE

To install a Dart Head Rest Assembly:

- 3.1 If installed, remove the existing Head Rest Assembly by pulling the quick release pin that attaches it to the seat. Make note of the installation position (if applicable).
- 3.2 Inspect the seat for damage in the vicinity of the Head Rest Assembly. Consult the Aircraft Maintenance Manual for disposition if damage is observed.
- 3.3 If only replacing the Head Rest with the equivalent Dart D3303-041 Head Rest, separate the existing Head Rest from the existing Tube Assembly by undoing 4 screws. Re-assemble D3303-041 Head Rest with existing Tube Assembly by installing 4 screws and tightening to 15-25 in lb.
- 3.4 If only replacing the Tube Assembly with a Dart D3304-041/-043/-044 Tube Assembly, separate the existing Head Rest from the existing Tube Assembly by undoing 4 screws. Re-assemble existing Head Rest with Dart D3304-041/-043/-044 Tube Assembly by installing 4 screws and tightening to 15-25 in lb.
- 3.5 Slide the new or modified Head Rest Assembly into the seat tube and lock in place at the same location that the old Head Rest Assembly was installed (if applicable) using the quick release pin. Ensure pin is properly engaged.

4.0 WEIGHT AND BALANCE

There is negligible weight change associated with the installation of the Dart Head Rests.

5.0 PARTS LIST

QTY -011	QTY -041	QTY -043	QTY -044	Part Number	Description
X				D412-724-011	Dart Replacement Head Rest Kit, for 205/212/412
2	X			D412-724-041	Head Rest Assembly, Center
1		X		D412-724-043	Head Rest Assembly, LH
1			X	D412-724-044	Head Rest Assembly, RH
	1	1	1	D3303-041	Head Rest
	1			D3304-041	Tube Assembly
		1		D3304-043	Tube Assembly
			1	D3304-044	Tube Assembly
	4	4	4	AN525-10R6	Screw